



## TP-3. Curved concrete box girder with compressive struts





### Overview


- Modeling a curved concrete box girder with compressive struts
- Geometry
  - Mirror
  - Fuse
  - Revolve
  - Rotate
  - Cut
- Mesh
  - Auto Mesh




## Step 1.




1. Analysis > Analysis Control – Control tab
2. Analysis Type : 3D
3. Click  Button (Unit System)
4. Length : m
5. Click on [OK] Button
6. Click on [OK] Button



## Step 2.



1. Geometry > Work Plane > Move...
2. Select the "Ref. Plane" tab
3. Select "XZ" plane as reference face
4. Click on [OK] Button
5. Toggle on "Normal" view



Step 3.

Vertex Coordinate Table

	X	Y	Z
1	0.0000	0.0000	0.0000
2	0.0000	0.0000	3.8100
3	0.0000	0.0000	3.5400
4	0.0000	0.0000	0.2300
5	-1.6300	0.0000	0.2300
6	-1.6300	0.0000	3.5400
7	-1.8800	0.0000	0.6600
8	-1.8800	0.0000	0.3300
9	-2.0000	0.0000	0.6600
10	-2.0000	0.0000	3.4000
11	-2.2200	0.0000	0.0000
12	-2.2700	0.0000	3.2900
13	-2.2700	0.0000	0.6600
14	-2.3900	0.0000	0.6600
15	-2.3900	0.0000	0.3500
16	-2.6400	0.0000	0.2700
17	-2.7700	0.0000	3.4900
18	-3.5400	0.0000	3.4900
19	-4.5800	0.0000	3.0200

Load from File...

☐ Make Vertices as Compound

OK

Cancel

X	Y	Z
0.00	0.00	0.00
0.00	0.00	3.81
0.00	0.00	3.54
0.00	0.00	0.23
-1.63	0.00	0.23
-1.63	0.00	3.54
-1.88	0.00	0.66
-1.88	0.00	0.33
-2.00	0.00	0.66
-2.00	0.00	3.40
-2.22	0.00	0.00
-2.27	0.00	3.29
-2.27	0.00	0.66
-2.39	0.00	0.66
-2.39	0.00	0.35
-2.64	0.00	0.27
-2.77	0.00	3.49
-3.54	0.00	3.49
-4.58	0.00	3.02
-4.79	0.00	3.48
-4.79	0.00	3.18
-4.95	0.00	3.03
-6.58	0.00	0.64
-6.77	0.00	1.05
-7.16	0.00	0.46
-7.16	0.00	1.04
-7.18	0.00	1.00
-7.29	0.00	0.67
-7.32	0.00	0.61
-10.95	0.00	2.87
-13.21	0.00	2.80
-16.73	0.00	3.16
-16.73	0.00	3.48
-17.82	0.00	3.81
-17.82	0.00	3.28

1. Geometry > Vertex > Tabular Input...

2. Copy the highlighted tabulated coordinates into the dialog box.

3. Click on [OK] Button

4. Toggle off "Toggle Grid"

5. Hide Datum & WP



Previous Command...

Toggle Grid

Grid Setting...

Move Work Plane...

☒ Toggle GCS Triad

☒ Toggle WCS Triad



Turn on All Triads

Turn off All Triads



Hide Datum & WP

Hide All Labels


## Step 4.




1. Geometry > Curve > Create on WP > line...
2. Toggle on "Vertex Snap"
3. Connect the nodes as shown in the picture
4. Click on [Cancel] Button




### Step 5.




1. *Geometry > Surface > Create > Plane Face ...*
2. *Select the highlighted edges*
3. *Click on [Apply] Button*





## Step 6.



1. *Geometry > Surface > Create > Plane Face ...*
2. *Select the highlighted edges*
3. *Click on [OK] Button*




## Step 7.









## Step 8.




1. Toggle on "Front" view
2. Geometry > Surface > Fuse ...
3. Select two highlighted faces
4. Click on [OK] Button
5. Select the highlighted lines and delete them



## Step 9.




1. Geometry > Work Plane > Move...
2. Select the "Tran & Rot" tab
3. Angle: 90 [Deg]
4. Click on [OK] Button
5. Toggle on "Isometric 1" view
6. Toggle on "Grid Snap"




## Step 10.


1. Geometry > Curve > Create on WP > Curve ...
2. Location: (300,0)
3. Select the starting point of the curve as shown in the picture
4. Draw the "Guide Curve" as shown in the picture (arbitrary length)
5. Click on [Cancel] Button
6. Toggle on "Top" view




## Step 11.




1. Geometry > Vertex > Create ...
2. Type: Conic Center
3. Select the curve as shown in the picture
4. Click on [OK] Button
5. Toggle on "Isometric 1" view




## Step 12.




1. *Geometry > Datum > Axis ...*
2. *Type: Vertex and Direction*
3. *Select the conic center for vertex*
4. *Select Z-Axis as reference direction*
5. *Click on [OK] Button*




### Step 13.




1. *Geometry > Generate Features > Revolve ...*
2. *Select all the faces*
3. *Select the new generated axis as reference axis*
4. *Tick on “Reverse Direction”*
5. *Angle: 30 [Deg]*
6. *Click on [OK] Button*




# Step 14.




1. Geometry > Work Plane > Move...
2. Select the "Tran & Rot" tab
3. Rotation: x-Axis
4. Angle: 90 [Deg]
5. Click on [OK] Button
6. Toggle on "Normal" view



## Step 15.




1. *Geometry > Curve > Create on WP > Rectangle (Wire)...*
2. *Tick on “Make Face”*
3. *Toggle on “Grid Snap” view*
4. *Draw an arbitrary face as shown in the picture*
5. *Click on [Apply] Button*
6. *Click on [Cancel] Button*








## Step 16.



1. *Geometry > Transform > Rotate ...*
2. *Select the highlighted face*
3. *Select the new generated axis as reference axis*
4. *Select “Uniform Copy”*
5. *Angle: -5 [Deg]*
6. *Number of Times: 5*
7. *Click on [OK] Button*




## Step 17.




1. Toggle on "Top" view
2. *Geometry > Transform > Rotate ...*
3. *Select 6 faces*
4. *Select the new generated axis as reference axis*
5. *Select "Uniform Copy"*
6. *Angle: -1 [Deg]*
7. *Number of Times: 1*
8. *Click on [OK] Button*



## Step 18.




1. *Geometry > Solid > Divide...*
2. *Select all the solid elements*
3. *Select 12 faces for "Tool Surface(s)"*
4. *Click on [OK] Button*




Step 19.


1. Select the highlighted segments and Delete them




## Step 20.



1. *Geometry > Boolean Operation > Fuse...*
2. *Select one segment as Boolean Master*
3. *Select other segments as Boolean Tool(s)*
4. *Check off Merge Faces*
5. *Click on [OK] Button*



## Step 21.



1. Mesh > Auto Mesh > Solid...
2. Select the solid model
3. Element size: 2
4. Property: 1
5. Click on [OK] Button

